THERMAL DEFORMATION INFLUENCE TO CRYOGENIC PUMPS SEALS OPERABILITY

© 2009 A. V. Ivanov

Voronezh State Technical University

The bush seals and seals with semi-movable rings are widely used in rocket engines turbopumps. One of abnormal function of this seals causes is – contact of rotor and stator elements. This occurs due to incorrect selection of seal clearance that connected with thermal deformations.

Seal, rotor, stator, thermal deformation, temperature coefficient of linear expansion, sealing clearance, chill-down

Ivanov Anderei Vladimirovich, candidate of Technical Science, associate professor of Voronezh State Technical University Rocket Engines Department. Voronezh, 394026, Moskovskiy Prospekt 14. Tel/ (4732) 34-61-08. E-mail: iav308@inbox.ru. Area of research: turbopumps, rotor dynamics, flow path seals.

References

- 1. Novitskiy L.A., Kozhevnikov I.G. Low temperature thermalphysic properties of materials. Handbook. M.: Mashinostroenie, 1975 216 pp.
- 2. Belousov A.I., Ivanov A.V. Structural features and behavior of seals in the hydrogen pump flow passages // Russian aeronautics, 2007, Vol. 50, № 1, Allerton press, pp. 37–40.